

Decision 88-04

<https://had.aer.ca/link/decision183>

TITLE

Examiner report on application by Husky Oil Operations Limited, 1988 (well site access road review)

DATE

1988

APPLICANT

Husky Oil Operations Ltd.

APPLICATION NUMBER

871530

HEARING PANEL

Homeniuk TF

HEARING TYPE

Examiners

CATEGORY

Production facility

DESCRIPTORS

Well licence

Well site
Accident
Grazing land
Liability (Law)
NTS 73E
Road construction
Safety

LEGAL REFERENCES

Energy Resources Conservation Act S42

NOTES

ERCB Examiners report E88-04 on application No. 871530 for a review of the licences governing access to wells located in LSD 3,5,13 of section 3, TP.52, R.4 W4M; Examiners meeting held 1988-01-06

LOCATION

03-03-052-04W4

05-03-052-04W4
13-03-052-04W4

Decision E58-(p.221)

<https://had.aer.ca/link/decision328>

TITLE

Examiners report on inquiry into a fire which occurred at Colorado et al N'Ville 11-9-79-22 well, 1958

DATE

1958

APPLICANT

Energy Resources Conservation Board

HEARING PANEL

Manyluk AF

Macleod NA

HEARING TYPE

Examiners

CATEGORY

Inquiry

DESCRIPTORS

Inquiry

Fire

Accident

Well fire

NOTES

Examiners report on inquiry into the cause of the fire at the said well on October 30, 1958; three possible causes for the fire; examiners find no evidence that the operator had been negligent